

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.


1

Date: 07/24/25

Direction Photo Taken: Upstream

Description:

72-inch outfall condition. Gully next to right wingwall (look upstream) and beginning of plunge pool (Project Area 1)



A=COM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

Date: 07/24/25

Direction Photo Taken: Right Bank

Description:

Left wingwall (looking upstream) condition. (Project Area 1)





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

3

Date: 07/24/25

Direction Photo Taken:

Downstream

Description:

Downstream condition of stream with concrete debris, unstable (soon to fall) trees, woody debris build up



A=COM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359


Photo No.

Date: 07/24/25

Direction Photo Taken: Left Bank

Description:

Concrete debris in the channel, downstream of Project Area 1





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

5

Date: 07/24/25

Direction Photo Taken:

Left Bank



Fallen trees causing debris build up in the channel. View from left bank. Between Project Area 1 and 2



AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.


Date: 07/24/25

Direction Photo Taken:

Downstream

Description:

Concrete debris in the channel, fallen trees, bank erosion and woody debris build up in channel between Project Area 1 and 2





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

7


Date: 07/24/25

Direction Photo Taken:

Left Bank

Description:

Eroding channel bank between Project Area 1 and 2



AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.


Photo No. 8

Date: 07/24/25

Direction Photo Taken: Downstream

Description:

Falling trees and debris build up in the stream between Project Area 1 and 2





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

9

Date: 07/24/25

Direction Photo Taken: Left Bank

Description:

36-inch outfall showing undercut of headwall and erosion of the left side



AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

Date: 07/24/25

Direction Photo Taken:

Downstream

Description:

Exposed sanitary sewer pipe next to 36-inch outfall (Project Area 2)





Project Name:

Taylor Run Stream Restoration

Project No.

Photo No. 11


Date: 07/24/25

Direction Photo Taken:

Left Bank

Description:

Severe bank erosion immediately downstream from the 36-inch outfall (Project Area 2)



AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.


Photo No. 12

Date: 07/24/25

Direction Photo Taken: Upstream

Description:

Upstream stream condition, standing at the 36-inch outfall. Fallen tree(s) due to bank instability (Project Area 2)





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.

Date: 07/24/25

Direction Photo Taken: Upstream/Right Bank

3089–3097 King St Alexandria VA



Description:

Exposed sanitary sewer manhole with undercut of concrete skirt

AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No.


Date: 07/24/25

Direction Photo Taken:

Downstream

Description:

Upstream stream condition from exposed sanitary sewer manhole (Project Area 3)





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 15

Date: 07/24/25

Direction Photo Taken:

Downstream

3099 King St Alexandria VA



Description:

Downstream conditions of the exposed sanitary sewer manhole. Woody Debris build up in the back. (Project Area 3)

AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 16

Date: 07/24/25

Direction Photo Taken: Upstream

Description:

Woody debris build up between Project Area 3 and Project Area 4. Falling trees from bank instalbility





Project Name:

Taylor Run Stream Restoration

Project No.

Photo No. 17


Date: 07/24/25

Direction Photo Taken:

Left Bank

Description:

Exposed root exposure of champion tree (Project Area 4)



AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 18

Date: 07/24/25

Direction Photo Taken: Upstream/Left Bank

Description:

Horizontal extent of root exposure of the champion tree (Project Area 4)





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 19

Date: 07/24/25

Direction Photo Taken: Downstream/Left Bank

3100 King St Alexandria VA



Description:

Leaning sheet pile wall and build of debris within the channel (Project Area 4)

AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359


Photo No. 20

Date: 07/24/25

Direction Photo Taken: Downstream

Description:

Exposed sanitary sewer pipe near sheet pile wall (Project Area 4)





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 21


Date: 07/24/25

Direction Photo Taken:

Upstream Left Bank



Exposed roots, stream bank erosion and gully formed from trail side runoff



AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.


Photo No. 22

Date: 07/24/25

Direction Photo Taken: Upstream

Description:

Condition of right bank, downstream of study extent





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 23

Description:


extent

Date: 07/24/25

Direction Photo Taken:

Downstream

3100 King St Alexandria VA





AECOM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 24

Date: 10/08/25

Direction Photo Taken: Right Bank

Description:

From center of sanitary manhole it is 2 feet from the sheet pile wall





Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 25

Date: 10/08/25

Direction Photo Taken:

Downstream

Description:

Outer extent of sanitary sewer manhole is 10 inches from the sheet pile wall



A=COM

SITE PHOTOGRAPH LOG

Project Name:

Taylor Run Stream Restoration

Project No.

60742359

Photo No. 26

Date: 10/08/25

Direction Photo Taken: Right Bank

Description:

Sanitary Sewer manhole is 19 feet from the start of the sheet pile wall

