



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 1	Date: 07/24/25	3210 King St Alexandria VA ☉ 301°NW (T) ● 38°49'23"N, 77°4'56"W ±13ft ▲ 160ft  Taylor Run 24 Jul 2025, 09:51:35	
Direction Photo Taken: Upstream			
Description: 72-inch outfall condition. Gully next to right wingwall (look upstream) and beginning of plunge pool (Project Area 1)			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 2	Date: 07/24/25	3210 King St Alexandria VA ☉ 249°W (T) ● 38°49'23"N, 77°4'56"W ±13ft ▲ 157ft  Taylor Run 24 Jul 2025, 09:51:42	
Direction Photo Taken: Right Bank			
Description: Left wingwall (looking upstream) condition. (Project Area 1)			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 3	Date: 07/24/25	3210 King St Alexandria VA ☉ 119°SE (T) ● 38°49'23"N, 77°4'56"W ±9ft ▲ 153ft  Taylor Run 24 Jul 2025, 09:53:21
Direction Photo Taken: Downstream		
Description: Downstream condition of stream with concrete debris, unstable (soon to fall) trees, woody debris build up		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 4	Date: 07/24/25	3210 King St Alexandria VA ☉ 192°S (T) ● 38°49'23"N, 77°4'56"W ±13ft ▲ 156ft  Taylor Run 24 Jul 2025, 10:07:08
Direction Photo Taken: Left Bank		
Description: Concrete debris in the channel, downstream of Project Area 1		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 5	Date: 07/24/25	3210 King St Alexandria VA ☉ 268°W (T) ● 38°49'22"N, 77°4'55"W ±13ft ▲ 150ft  000042 Taylor Run 24 Jul 2025, 10:10:56
Direction Photo Taken: Left Bank		
Description: Fallen trees causing debris build up in the channel. View from left bank. Between Project Area 1 and 2		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 6	Date: 07/24/25	3210 King St Alexandria VA ☉ 310°NW (T) ● 38°49'22"N, 77°4'55"W ±29ft ▲ 156ft  000042 Taylor Run 24 Jul 2025, 10:11:13
Direction Photo Taken: Downstream		
Description: Concrete debris in the channel, fallen trees, bank erosion and woody debris build up in channel between Project Area 1 and 2		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 7	Date: 07/24/25	3210 King St Alexandria VA ☉ 55°NE (T) ☉ 38°49'22"N, 77°4'55"W ±13ft ▲ 151ft  Taylor Run 24 Jul 2025, 10:12:48
Direction Photo Taken: Left Bank		
Description: Eroding channel bank between Project Area 1 and 2		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 8	Date: 07/24/25	3210 King St Alexandria VA ☉ 318°NW (T) ☉ 38°49'21"N, 77°4'52"W ±9ft ▲ 143ft  Taylor Run 24 Jul 2025, 10:16:46
Direction Photo Taken: Downstream		
Description: Falling trees and debris build up in the stream between Project Area 1 and 2		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 9	Date: 07/24/25	3210 King St Alexandria VA ☉ 4°N (T) ☉ 38°49'20"N, 77°4'52"W ±9ft ▲ 139ft  Taylor Run 24 Jul 2025, 10:25:45	
Direction Photo Taken: Left Bank			
Description: 36-inch outfall showing undercut of headwall and erosion of the left side			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 10	Date: 07/24/25	3210 King St Alexandria VA ☉ 77°E (T) ☉ 38°49'20"N, 77°4'52"W ±13ft ▲ 142ft  Taylor Run 24 Jul 2025, 10:26:04	
Direction Photo Taken: Downstream			
Description: Exposed sanitary sewer pipe next to 36-inch outfall (Project Area 2)			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 11	Date: 07/24/25	3210 King St Alexandria VA ☀ 117°SE (T) ● 38°49'19"N, 77°4'51"W ±9ft ▲ 155ft  Taylor Run 24 Jul 2025, 10:48:11
Direction Photo Taken: Left Bank		
Description: Severe bank erosion immediately downstream from the 36-inch outfall (Project Area 2)		




SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 12	Date: 07/24/25	3210 King St Alexandria VA ☀ 328°NW (T) ● 38°49'21"N, 77°4'52"W ±9ft ▲ 137ft  Taylor Run 24 Jul 2025, 10:25:49
Direction Photo Taken: Upstream		
Description: Upstream stream condition, standing at the 36-inch outfall. Fallen tree(s) due to bank instability (Project Area 2)		




SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 13	Date: 07/24/25	3089–3097 King St Alexandria VA ☉ 331°NW (T) ☉ 38°49'15"N, 77°4'48"W ±13ft ▲ 144ft  Taylor Run 24 Jul 2025, 10:54:52	
Direction Photo Taken: Upstream/Right Bank			
Description: Exposed sanitary sewer manhole with undercut of concrete skirt			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 14	Date: 07/24/25	3099 King St Alexandria VA ☉ 320°NW (T) ☉ 38°49'15"N, 77°4'48"W ±9ft ▲ 133ft  Taylor Run 24 Jul 2025, 10:55:54	
Direction Photo Taken: Downstream			
Description: Upstream stream condition from exposed sanitary sewer manhole (Project Area 3)			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 15	Date: 07/24/25	3099 King St Alexandria VA ☉ 164°S (T) ☉ 38°49'15"N, 77°4'48"W ±9ft ▲ 128ft  Taylor Run 24 Jul 2025, 10:55:57	
Direction Photo Taken: Downstream			
Description: Downstream conditions of the exposed sanitary sewer manhole. Woody Debris build up in the back. (Project Area 3)			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 16	Date: 07/24/25	3089–3097 King St Alexandria VA ☉ 170°S (T) ☉ 38°49'14"N, 77°4'47"W ±42ft ▲ 141ft  Taylor Run 24 Jul 2025, 10:58:42	
Direction Photo Taken: Upstream			
Description: Woody debris build up between Project Area 3 and Project Area 4. Falling trees from bank instability			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 17	Date: 07/24/25	3100 King St Alexandria VA ☀ 101°E (T) ● 38°49'14"N, 77°4'48"W ±13ft ▲ 146ft  Taylor Run 24 Jul 2025, 11:01:17
Direction Photo Taken: Left Bank		
Description: Exposed root exposure of champion tree (Project Area 4)		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 18	Date: 07/24/25	3100 King St Alexandria VA ☀ 45°NE (T) ● 38°49'13"N, 77°4'48"W ±9ft ▲ 141ft  Taylor Run 24 Jul 2025, 11:03:30
Direction Photo Taken: Upstream/Left Bank		
Description: Horizontal extent of root exposure of the champion tree (Project Area 4)		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 19	Date: 07/24/25	3100 King St Alexandria VA ☀ 147°SE (T) ● 38°49'13"N, 77°4'48"W ±45ft ▲ 131ft  Taylor Run 24 Jul 2025, 11:06:04
Direction Photo Taken: Downstream/Left Bank		
Description: Leaning sheet pile wall and build of debris within the channel (Project Area 4)		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 20	Date: 07/24/25	3100 King St Alexandria VA ☀ 208°SW (T) ● 38°49'13"N, 77°4'48"W ±13ft ▲ 136ft  Taylor Run 24 Jul 2025, 11:06:19
Direction Photo Taken: Downstream		
Description: Exposed sanitary sewer pipe near sheet pile wall (Project Area 4)		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 21	Date: 07/24/25	3100 King St Alexandria VA ☀ 62°NE (T) ● 38°49'12"N, 77°4'48"W ±101ft ▲ 145ft  Taylor Run 24 Jul 2025, 11:13:50	
Direction Photo Taken: Upstream Left Bank			
Description: Exposed roots, stream bank erosion and gully formed from trail side runoff			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 22	Date: 07/24/25	3100 King St Alexandria VA ☀ 31°NE (T) ● 38°49'12"N, 77°4'48"W ±13ft ▲ 143ft  Taylor Run 24 Jul 2025, 11:14:06	
Direction Photo Taken: Upstream			
Description: Condition of right bank, downstream of study extent			




SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 23	Date: 07/24/25	3100 King St Alexandria VA ☀ 135°SE (T) ● 38°49'12"N, 77°4'48"W ±32ft ▲ 148ft  Taylor Run 24 Jul 2025, 11:19:00	
Direction Photo Taken: Downstream			
Description: Condition of the stream downstream of study extent			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359	
Photo No. 24	Date: 10/08/25	South East Elevation ☀ 309°NW (T) ● 38°49'13"N, 77°4'48"W ±13ft ▲ 138ft  08 Oct 2025, 16:01:18	
Direction Photo Taken: Right Bank			
Description: From center of sanitary manhole it is 2 feet from the sheet pile wall			



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 25	Date: 10/08/25	North Elevation ☉ 202°S (T) ☉ 38°49'13"N, 77°4'48"W ±13ft ▲ 139ft  08 Oct 2025, 16:00:11
Direction Photo Taken: Downstream		
Description: Outer extent of sanitary sewer manhole is 10 inches from the sheet pile wall		



SITE PHOTOGRAPH LOG

Project Name: Taylor Run Stream Restoration		Project No. 60742359
Photo No. 26	Date: 10/08/25	North Elevation ☉ 202°S (T) ☉ 38°49'13"N, 77°4'48"W ±13ft ▲ 136ft  08 Oct 2025, 16:00:07
Direction Photo Taken: Right Bank		
Description: Sanitary Sewer manhole is 19 feet from the start of the sheet pile wall		